



YASKAWA

Discontinuation

L1000A series | CIMR-LCxxxxxxxx-9130
08/2026 | V1

Life Cycle Phase Change Information

The Yaskawa L1000A series of elevator drives was introduced to the European market in 2009 as a specialized, high-performance drive for controlling geared and gearless lift motors.

After 17 years of successful field operation, we are facing difficulties in sourcing spare parts for the L1000A series and have decided to extend the phase-out process for the COSMOS product family.

The L1000A model is being replaced by our latest premium lift model, the LA700. Yaskawa Europe premium lift product can be identified by the model code CIPR-LA70Cxxxxxxxx-xxxxxx-9600.

Model(s) to be discontinued

L1000A series CIMR-LCxxxxxxxx-9130

Last Order Acceptance

September 30th, 2026 | depending parts availability

Last Shipment

February 28th, 2027

Replacement of 400V Products

Old SAP No.	Previous Model (L1000A)	New SAP No.	Replacement Model (LA700)
10009220	CIMR-LC4F0005BAC-9130		
10009222	CIMR-LC4F0006BAC-9130		
10000594	CIMR-LC4F0009BAC-9130	10115850	CIPR-LA70C4012CBAA-HAAAAA-9600
10000595	CIMR-LC4F0015BAC-9130	10115852	CIPR-LA70C4019CBAA-HAAAAA-9600
10000596	CIMR-LC4F0018BAC-9130	10115854	CIPR-LA70C4023CBAA-HAAAAA-9600
10000597	CIMR-LC4F0024BAC-9130	10115856	CIPR-LA70C4030CBAA-HAAAAA-9600
10000598	CIMR-LC4F0031BAC-9130	10115858	CIPR-LA70C4039CBAA-HAAAAA-9600
10000599	CIMR-LC4F0039BAC-9130	10116078	CIPR-LA70C4049CBAA-HAAAAA-9600
10009236	CIMR-LC4F0045BAC-9130	10116080	CIPR-LA70C4056CBAA-HAAAAA-9600
10000600	CIMR-LC4F0060BAC-9130	10116081	CIPR-LA70C4075ABAA-HAAAAA-9600
10009240	CIMR-LC4F0075BAC-9130	10116082	CIPR-LA70C4094ABAA-HAAAAA-9600
10009242	CIMR-LC4F0091BAC-9130	10116083	CIPR-LA70C4114ABAA-HAAAAA-9600
10009244	CIMR-LC4F0112CAC-9130	10116084	CIPR-LA70C4140ABAA-HAAAAA-9600
10009246	CIMR-LC4F0150CAC-9130	10116085	CIPR-LA70C4188ABAA-HAAAAA-9600
10009247	CIMR-LC4F0180CAC-9130	10116086	CIPR-LA70C4225ABAA-HAAAAA-9600
10009248	CIMR-LC4F0216CAC-9130	10116087	CIPR-LA70C4270ABAA-HAAAAA-9600
		10116088	CIPR-LA70C4325ABAA-HAAAAA-9600
		10116089	CIPR-LA70C4380ABAA-HAAAAA-9600

* For 200V products replacement please contact you nearest Yaskawa sales responsible.

Service Information

Differences in product specifications

The L1000A can be easily replaced by the LA700 For installations requiring CANlift, this function will be available via a firmware update by the end of 2026.

Sales Materials

Sales materials will not be longer printed.

Handling of Existing Orders

All confirmed orders will be continued. From 30th September 2026 no more new orders will be accepted.

Repair and Spare Parts

For more information on the availability services like spare parts or repair please contact Yaskawa After Sales Service Department.

[YEUD Aftersales](#) | [YEUD Repair](#)

General Information Support Availability

During the phase out time, Yaskawa cannot guarantee full product support, such as replacement possibilities, due to limited component availability.

Note that manufacturers supplying components which are necessary for replacement or repair may discontinue production prior to Yaskawa phase out of spare parts supply or repair timeline.

For more information on the availability services like spare parts or repair please contact Yaskawa After Sales Service Department: support@yaskawa.eu



Adrian Lischka

Product Manager Drives
Business Unit Drives

Mark Simms

Segment Manager Lift
Business Unit Drives

YASKAWA Europe GmbH

Drives Motion Controls Division
Philipp-Reis-Straße 6
65795 Hattersheim
Germany

www.yaskawa.eu.com

© Yaskawa Europe GmbH. All rights reserved.